

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S9	2661	(219/137.\$).CCLS.	US-PGPUB; USPAT; USOCR; FFRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/12/19 13:10
S10	1384	S9 and arc welding	US-PGPUB; USPAT; USOCR; FFRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/12/19 13:11
S11	25	S9 and (arc welding with cycle)	US-PGPUB; USPAT; USOCR; FFRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/12/19 13:11
S12	2661	(219/137.\$).CCLS.	US-PGPUB; USPAT; USOCR; FFRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/12/19 13:23
S13	18	S12 and (arc welding with cycle with electrode)	US-PGPUB; USPAT; USOCR; FFRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/12/19 13:23
S16	14394	("373").CLAS.	US-PGPUB; USPAT; USOCR; FFRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/12/23 14:39
S22	396	(219/137.137,137.7).CCLS.	US-PGPUB; USPAT; USOCR; FFRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/05 17:39
S23	2663	(219/137.\$).CCLS.	US-PGPUB; USPAT; USOCR; FFRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/05 17:48

S24	65	S23 and (feedback with voltage)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/05 17:48
S26	2663	(219/137.\$).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/06 07:59
S27	104	S26 and (shield\$3 gas and carbon dioxide)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/06 07:59
S31	2663	(219/137.\$).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/06 18:14
S32	18	S31 and sampling	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/06 18:14
S35	3642	(219/130.\$).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/07 09:32
S36	278	S35 and samp\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 09:32
S37	33	S35 and (dip with transfer\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 11:14
S40	3642	(219/130.\$).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/07 15:56

S41	73	S40 and samp1\$3 and (advanc\$3 with (wire or electrode))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 15:56
S43	396	(219/137.7).OCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/07 16:59
S45	7	S43 and samp1\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 17:00
S49	2663	(219/137.\$).OCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/07 17:11
S50	1	S49 and samp1\$3 with (advanc\$3 with (wire or electrode))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 17:11
S51	156	weld\$3 and (arc welding with cycle with electrode)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 17:14
S52	57	weld\$3 and samp1\$3 with (advanc\$3 with (wire or electrode))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 17:19
S53	3	((weld\$3 method) or (weld\$3 process)) and samp1\$3 with (advanc\$3 with (wire or electrode))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 17:25
S54	410	(219/137.2).OCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/07 17:32

S55	1	S54 and samp1\$3 with (advanc\$3 with (wire or electrode))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 17:33
S56	6	S54 and samp1\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 17:34
S57	25082	((219/137.&) or (219/130.\$) or (219/121.\$) or (219/121.\$)). COLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/07 17:39
S58	1	S57 and samp1\$3 with (advanc\$3 with (wire or electrode))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 17:40
S59	31702	((weld\$3 method) or (weld\$3 process)) and (referenc\$3 or samp1\$3 signal with (advanc\$3 with (wire or electrode)))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 18:08
S60	2095	S59 and ((rate or speed) with electrode)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 18:10
S61	31707	((weld\$3 method) or (weld\$3 process)) and (referenc\$3 or samp1\$3 signal)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 18:11
S62	6433	S61 and (regulat\$3 or control\$3 with electrode)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 18:12
S69	3	((weld\$3 method) or (weld\$3 process)) and (referenc\$3 with signal with regulat\$ with rate with electrode)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 18:25

S70	48	((weld\$3 method) or (weld\$3 process)) and (((referenc\$3 or samp\$3 signal) with (advanc\$3 with (wire or electrode)))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 18:30
S71	1	((weld\$3 method) or (weld\$3 process)) and (((referenc\$3 or samp\$3 signal) with (advanc\$3 with (wire or electrode)))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/07 18:32
S85	490	weld\$3 with samp1\$3 with (electrode or wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 10:00
S86	20	weld\$3 with samp1\$3 with rate with (electrode or wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 10:02
S87	19	("5166491" "5321229" "5805442" "5808885" "6000429" "6002104" "6018136" "6169263" "6243611").RN. OR ("6479792").URPN.	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/11 10:08
S88	13	("2529111" "2836102" "2873402" "3530359" "3538376" "3614377" "3728516" "3731049").PN.	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/11 10:12
S91	3730	weld\$3 with reference with (electrode or wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 10:26
S92	115	weld\$3 with reference with rate with (electrode or wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 10:26
S97	2663	(219/137-\$).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/11 10:53

S98	7	S97 and sampl\$3 with rate	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 10:53
S99	10	S97 and sampl\$3 with (electrode or wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 10:56
S100	396	(219/137.7).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/11 11:04
S102	785	(219/137.7,137.2).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/11 11:05
S104	1	S102 and sampl\$3 with rate	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:05
S106	14	weld\$3 process with sampl\$3 with electrode	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:08
S108	2018	((weld\$3 method) or (weld\$3 process)) with (referenc\$3 or signal)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:27
S109	84	S108 with rate	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:28
S110	212	((weld\$3 method) or (weld\$3 process)) with (sampl\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:29

S111	14	((weld\$3 method) or (weld\$3 process)) with (sampl\$3) with rate	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:29
S113	26	((weld\$3 method) or (weld\$3 process)) with (reference) with rate	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:36
S116	83	((weld\$3 method) or (weld\$3 process)) with (regulat\$3) with electrode	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:46
S117	15	((weld\$3 method) or (weld\$3 process)) with (regulat\$3) with rate with electrode	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:51
S118	35	((weld\$3 method) or (weld\$3 process)) with (regulat\$3) with rate	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 11:53
S121	27	weld\$3 with sampl\$3 with control\$3 with (electrode or wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 12:18
S127	10	weld\$3 with reference with regulate with electrode	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 12:47
S128	350	weld\$3 with regulate with electrode	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 12:51
S130	5	weld\$3 with control\$3 with melt rate	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 14:07

S131	8080	weld\$3 with control\$3 with (current or volatile or melt)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 14:10
S132	70	S131 with (sampl\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 14:10
S133	462	S131 with (reference)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 14:29
S135	9416	weld\$3 with control\$3 with (current or voltage or melt)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 14:30
S136	130	S135 with (sampl\$3 or (reference signal))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/01/11 14:31

1/15/2009 2:20:31 PM

C:\Documents and Settings\hnguyen45\My Documents\EAST\Workspaces\10516721.wsp